#### United States of America

### Department of Transportation—Federal Aviation Administration

## Supplemental Type Certificate

Number SA1088SO

This certificate, issued to

Aeronautical Engineers, Inc. P.O. Box 661027 Miami, Florida 33166

Added Notes at Surrender:

- Future unsafe conditions existing in the product can result in an airworthiness directive requiring correction of the unsafe condition before further flight. If there is no entity to comply with 14 CFR 21.99(a), Required design changes, the existence of an unsafe condition might result in permanently grounding of the aircraft.
  - Replacement palts inight not be available in the

certifies that the change in the type design for the following product with the limitation

therefor as specified hereon meets the airworthiness requirements of Part

STC Surrender processed:

Regulations.

Original Product - Type Certificate Number: 4A25

řoval by: 🖊

Date: 10/20/2007

McDonnell Douglas

*3*3, -41, -42, -43, -51,

Model:

DC-8-21

Description of Trype Design Change:

Installation of a cargo interior in accordance \with Aeronautical Engineers, Inc., Report No. R-404, "Drawing List, Cargo Configuration, DC-8," dated May 15, 1979 or later FAA apprøved revisi

Limitations and Conditions

Page

supporting data which is the basis for approval shall remain in effect until surrendered, specified, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application:

October 14, 1972

Date reissued:

Date of issuance:

July 11, 1979

Sale amended: October 28, 1982

By direction of the Administrator

ohn R. James

Acting Manager, Atlanta

<u> Aircraft Certification Office</u>

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

### United States of America

Department of Transportation—Federal Aviation Administration

# Supplemental Type Certificate

(Continuation Sheet)

Number SA1088SO

Limitations and Conditions: Approval of this change in type design and basically to McDonnell DC-8-21, -31, -32, -33, -41, -42, -43, -51, -52, -53, and -55 airplanes only. This approval should not be extended to other airplanes of this model on which other previously approved modifications are incorporated unless it is determined that the interrelationship between these various modifications will have no adverse affect(on the airworthiness of the airplane. This determination should consider weight or weight distribution changes. Aeronautical Engineers, Inc., Report R 388 "Loading Chart and Actual Weight and Balance, DC-8," dated May 15, 1979, Report R-394, "Cargo Loading in DC-8 Type Aircraft," dated May 7, 1979, and Report R-533-1, "Airplane Flight Manual Supplement for McDonnell Douglas DC-8-20, -30, -40, -50 Series," dated October 28, 1982, are required parts of this STC.

Date Issued: July 11, 1979

Date Amended: October/

..END....